

VINING SHIPBROKERS LTD

TYPE OF VESSEL Launch _____ sta Ha _____

LOA 41' _____ LWL _____

BEAM _____ DRAFT _____

YEAR 1989 _____ RIG _____

BUILDER Gary Dick - Boatbuilder AKLD _____

DESIGN Pelin Challenger _____

CONSTRUCTION GRP hull, timber/ply topsides
glassed. Full exterior Prof respray 2006.

TYPE HULL Hard chine, planing.

ENGINE 380HP 3208 Cat dsl (Underfloor, shaft)
(New 1989, total hours from new 2200)

CONDITION Excellent. 600hrs from full rebuild 2004.

GEARBOX MG507-1 hydraulic

SPEED CRG 16kts _____ MAX 21kts

FUEL CAPACITY 1000L (two s/s tanks)

WATER CAPACITY 500L (two s/s tanks)

Very well set up flybridge with vhf, sndr, gps/plotter,
controls for bowthruuster & capstan (all repeated
below), plus good seating & fridge.

A top example of this popular sought after design...
presented in excellent all round condition. Engine
room & motor present like new.

PRICE \$245,000 _____

BERTHS 6-8 _____ H/ROOM Full

TOILET Electric flush & holding tank

COOKER LPG. 4 burner / grill / oven.

NAV. GEAR Compass x 2, Furuno 1850D colour gps/
plotter, Furuno 1800 24m radar, Furuno FCV668
colour sndr, VHF R/T x 2, Robertson AP1000
autopilot.

GROUND TACKLE Plough anchor & full chain, plough
anchor plus chain/warp.

CAPSTAN Auto-Electric _____ Fire Ext 3

DINGHY _____

TRAILER _____

SAFETY EQUIPMENT MRB4 EPIRB, 8 lifejackets, gas
solenoid, gas detector, two electric bilge pumps (1
auto), windscreen wiper.

MISC H&C pressure water (h/w off motor), inside &
c/pit showers, fridge & freezer (off mtr compressor)
plus 12v fridge on flybridge, pots/pans/cutlery/
crockery, CD stereo, cassette stereo, clock &
barometer, Webasto 3500 diesel fired central heating,
leather upholstery in saloon, BOW THRUSTER, elec/
hydraulic trim tabs, dual station Sea Star hydraulic
controls, flybridge cover, flybridge bimini & clears,
electric scallop/line davit on stern, game rigged, live
bait tank, s/s gas bottle, c/pit basin, c/pit cover, scallop
dredge, spare long warp, 4 fenders, boathook, deck
wash fwd & aft, full manuals, three extra h/d 12v
batteries (2 systems).



The above information is believed to be correct but is not guaranteed. We are acting as brokers passing along information received from the boat's owner or his agent. No representations about the boat's physical condition are made.

VL3882

ERROR: syntaxerror
OFFENDING COMMAND: --nostringval--

STACK:

/Title
()
/Subject
(D:20111021103017+13'00')
/ModDate
()
/Keywords
(PDFCreator Version 0.9.5)
/Creator
(D:20111021103017+13'00')
/CreationDate
(Desktop)
/Author
-mark-