

VINING SHIPBROKERS LTD

TYPE OF VESSEL Yacht _____ sus Nel _____
LOA 30' _____ LWL _____
BEAM 20' _____ DRAFT 0.5-1.5m _____
YEAR 1994 _____ RIG _____
BUILDER Heritage Manufacturing South Africa _____
DESIGN Sagitta 30 - Richard Woods (UK) _____
CONSTRUCTION Airex foam sandwich _____
Lar keels, 5 x buoyancy areas in each hull, collision bulkheads, semi balanced rudders _____
TYPE HULL Catamaram _____
ENGINE 2 x 9.9hp Yamaha outboards _____
CONDITION New Dec 2001, 150 Hours _____
GEARBOX Yamaha, 11.75 x 9.25 pitch props _____
SPEED CRG 6 Kts _____ MAX _____
FUEL CAPACITY 160 Litres (2 x Alloy) _____
WATER CAPACITY 240 Litres (2 x PVC) _____
SPARS Alloy (serviced 2004) _____
RIGGING Stainless Steel, twin forestays _____
SAILS 2 x Mainsail - 1 new (with lazy jacks), 2 x furling headsail - 1 new, 1 x MPS in sock _____
REEFING Slab main, furling headsail _____
WINCHES Harken 2 x 32 - 2 speed self-tailing, 2 x 16 - single speed self-tailing, 3 x winch handles _____

PRICE \$140,000 _____
BERTHS 7 (3 x dble) _____ H/ROOM _____
TOILET Manual marine _____
COOKER LPG: Stove _____
NAV. GEAR Polare Riviera Genova compass, Tacktick wireless speed/log, sounder & windgear, Icom IC-M56 vhf r/t, Autohelm ST4000 Autopilot with ST000 remote, Garmin 130 gps/chartplotter _____
GROUND TACKLE 2 x Anchors, chain & warp _____
CAPSTAN _____ Fire Ext Yes _____
DINGHY Small inflatable & 1997 2hp Yamaha outboard TRAILER _____
SAFETY EQUIPMENT 1 x Electric & 3 x manual bilge pumps, some lifejackets & safety harnesses, flares (oos), Drogue and parachute anchor, 2 x liferings, southern ocean wet weather gear & built in harness. _____
MISC Cold pressure water, shower, 3 way fridge/fzr, Zip wall Kerosine cabin heater, Sony Xplod cd/am/fm mp3 stereo (new), Teak tv/dvd, gas bottle, boathook, fenders, cockpit dodger, boom cover, new fwd trampolines 2006, swim platform & boarding ladder, vessel has built in positive buoyancy. _____
Vessel cruised from South Africa to NZ via Atlantic, Panama Canal, Pacific, Fiji, New Caledonia _____



The above information is believed to be correct but is not guaranteed. We are acting as brokers passing along information received from the boat's owner or his agent. No representations about the boat's physical condition are made.

VY5214