

VINING SHIPBROKERS LTD

TYPE OF VESSEL Launch _____ mv Gis

LOA 45' _____ LWL _____

BEAM 12'6" _____ DRAFT 4' _____

YEAR 1936 _____ RIG - _____

BUILDER Collings and Bell _____

DESIGN Collings and Bell _____

CONSTRUCTION 4 Skin Kauri, Decks and Cabin Ply
Over Kauri Glassed Over _____

TYPE HULL Round Bilge, Displacement _____

ENGINE 6 Cylinder Gardner Diesel _____

CONDITION 500 Hours From Full Rebuild _____

GEARBOX Hydraulic New 2009 _____

SPEED CRG 7-8 Knots _____ MAX 9 Knots _____

FUEL CAPACITY 300 Litres Approx _____

WATER CAPACITY 120 Litres Approx _____

Vessel in 2004 / 05 underwent extensive
professional refit including total repaint, decks
refibreglassed, completely rewired, new shaft and
bearings, interior refit with new galley, toilet, carpets,
upholstery, panelling, top end overhaul of engine &
gearbox, new electronics, steering, anchor winch,
anchor and chain, batteries, etc _____

PRICE \$98,000 _____

BERTHS 7 (1 x Double) _____ H/ROOM 6' 2" _____

TOILET Electric Marine Flush & Holding Tank _____

COOKER LPG 2 x Burner & Grill plus Microwave Oven _____

NAV. GEAR Raymarine VHF Radio plus separate
Hand Held VHF, Compass, Raymarine ST 5000+ Auto
Pilot, Furuno 1715 Radar, Furuno GP-1650WF colour
GPS/Plotter, _____

GROUND TACKLE CQR Anchor, 100 metres Chain _____

CAPSTAN Auto Electric _____ Fire Ext x 2 _____

DINGHY No _____

TRAILER _____

SAFETY EQUIPMENT MT 300 EPIRB, 3 x Auto Electric
Bilge Pumps, 1 x Window Wiper, Fixed Spotlight,
First Aid Kit, Life-Jackets _____

MISC 12v Isotherm Fridge and Separate Freezer,
Hot & Cold Pressurised Water - hot via LPG Caliphont,
Shower, Separate 12v Starting & Domestic Batteries
with Emergency Link, 1000 Watt Inverter / Charger,
230v Shore Power, Large Magma BBQ, AM/FM
Radio/CD Stereo Player, Galley Equipment, Hydraulic
Steering, 9 KG LPG Cylinder, 4 x Fenders, Berthing
Lines, Swimming Ladder, Rod Holders, Fish Filleting
Board, Salt Water Deck Wash Pump, Boat Hook, 2hp
o/b.
Private Double Cabin, Twin Exterior Side Doors Off
Wheel House, Easy Walk Around Side Decks _____



The above information is believed to be correct but is not guaranteed. We are acting as brokers passing along information received from the boat's owner or his agent. No representations about the boat's physical condition are made.

VL3830